

BCC DS  
RECEIVED  
16/06/2026  
APPLICATION REF  
A006982385



# UTILITY MAP REPORT

<b>PROJECT LOCATOR</b>	Ryan Bradbury
<b>DATE</b>	25/05/2026
<b>SITE ADDRESS</b>	15 Villa Street, Annerley
<b>CLIENT</b>	Insight Planning Development
<b>SITE CONTACT</b>	Anthony Colwell
<b>CLIENT EMAIL</b>	anthony@insightplandev.com.au
<b>CLIENT NUMBER</b>	0413 608 612

AUS CERTLOC Certified Locating Organisation • AS 5488.1 – 2019 Compliant

### Detection Limitations

Utility locating, combined with electronic locating methods and Ground Penetrating Radar (GPR), is the most reliable method for identifying subsurface services prior to excavation or construction. However, as with any detection method, it is important to understand that not all services can be guaranteed to be located. While every reasonable step is taken to identify services within the specified area and fulfil duty of care obligations under AS 5488.1–2019, certain factors may limit detection. Small or non-metallic services may not be detectable, and some services may be obscured by reinforcing materials, soil conditions, or other subsurface objects.

### Interference Factors

Certain surface treatments, including concrete toppings, waterproofing membranes, and foil layers, can interfere with GPR and electromagnetic (EMF) signals, making detection difficult or impossible. Live cables with no active current draw, cables from unrelated circuits, and services in multi-tenant buildings that pass through the survey area may remain undetected. It is advisable to engage the relevant asset owners and obtain all available service drawings before work commences.

### Critical & High-Risk Services

When working near critical services — including gas mains, high-voltage cables, and fire alarm systems — the relevant asset owner and emergency services should be notified prior to commencement. A Safe Work Method Statement (SWMS) must be developed and followed. Some alarm and suppression system cables could trigger sprinkler or fire suppression systems; this must be confirmed with building management before any works begin.

### Electrical Safety

All electrical services within the work zone should be de-energised before any cutting, sawing, or drilling commences. If de-energising is not feasible, appropriate electrical safety precautions must be in place to protect all operators and bystanders. An electrician should be engaged to trace all circuits from the distribution board prior to scanning where possible.

### Operational Precautions

Conduits and services may be bundled or tied to steel reinforcement, rendering individual identification difficult. A minimum clearance of 25 mm on either side of all marked targets must be maintained during cutting or drilling. Objects located within 100 mm of walls, edges, or corners may not be detected unless scanned from the opposite side. If unexpected metal filings appear, or if water is encountered during drilling, all works must cease immediately. Do not drill more than 20% deeper than the reported slab or pavement thickness.

### Potholing Requirement

In accordance with AS 5488.1–2019, all subsurface services must be positively identified via potholing (Non-Destructive Digging) prior to construction or excavation to confirm the exact depth, alignment, and service type. Electronic locating and GPR alone constitute Quality Level B data and are not a substitute for Quality Level A (pothole) verification. Provac Australia offers Non-Destructive Digging services using Hydro Vacuum Excavation — contact 1300 734 772 for further information.

### Liability

While every effort is made to identify potential subsurface hazards, the technology and methods used cannot guarantee detection of all risks. Provac Australia does not warrant that all hazards have been identified. Although locating equipment is carefully operated to gather accurate data, Provac Australia cannot be held responsible for inaccuracies, misinterpretations, or damage arising from undetected services. Any structural or design-related interpretations must be verified by a qualified engineer. Results from utility locating surveys should be treated as supplementary information and not definitive conclusions until confirmed by engineering drawings or professional verification. This report has been prepared in accordance with AS 5488.1–2019 Classification of Subsurface Utility Information.

## SITE CONDITIONS

BYDA PLANS SUPPLIED	INTERNAL PLANS PROVIDED	CLIENT ONSITE	GPR DATA QUALITY
Yes	Yes	Yes	Good
No	No	No	Average
			Poor

## SCOPE OF WORKS

CCTV investigation on stormwater assets conflicting with scope of works.

## LOCATABLE ASSETS CHECKLIST

Confirm all applicable services have been located and marked prior to signing off this report.

Electrical (HV)	ORANGE	Water (Potable)	BLUE	Stormwater	GREEN
Electrical (LV)	ORANGE	Recycled Water	PURPLE	Fuel / Petroleum	BROWN
Telecommunications	WHITE	Sewer	CREAM	Fire Services	RED
NBN		Rising Sewer Main	CREAM	Unknown / Unidentified	PINK
Optus					
Pipe Networks					
AAPT					
Vocus					
Powerlink					
Other – specify					
Gas	YELLOW				

After today's investigations, it **appears possible** that the stormwater assets no longer exist.

This pit is not visible as may be built over or not existing.

Unable to find this pit due to the dense scrub and debris within the back yard.

Unable to access the pipe from this pit, as it drops into another chamber. The required pipe enters through the chamber wall, and attempts to navigate the crawler into the pipe were unsuccessful due to limited access. Please refer to the photo provided in the email.

This pit is not visible as may be built over or not existing.

Trench #1  
Trench depth approximately 1.4m to 1.6m  
Offsets:  
8.65m from the north western boundary fence.  
1.65m from the retaining wall.  
Please see photos on the following page.

I tried using a push camera to locate pit from Downpipe but was unsuccessful due to the mass amount of debris and silt within the piping.

North eastern fence.

North western fence.

Retaining wall.

HIGHLY RECOMMEND NON DESTRUCTIVE DIGGING SERVICES IN THIS AREA

**DISCLAIMER**

Pothole all services prior to construction to confirm the exact depth & alignment to Quality Level A.

Please refer to the Utility Locating Process & Duty of Care at the bottom of this report.


**EXCAVATION DISCLAIMER**  
SERVICE ALIGNMENT AND DEPTH IS REQUIRED TO BE CONFIRMED THROUGH A NON DESTRUCTIVE DIGGING PROCESS BEFORE MECHANICAL EXCAVATION TAKES PLACE

Trench #3  
Trench depth approximately 1.4m to 1.8m  
Offsets:  
1.3m from the north western boundary fence.  
8.5m from the retaining wall.

Trench #2  
Trench depth approximately 1.5m to 1.8m.  
Offsets:  
1.3m from the north eastern boundary fence.  
14.85 from the south western boundary fence.

sorth western fence.

SCOPE OF WORKS





**AS 5488.1 – 2019 CLASSIFICATION OF SUBSURFACE UTILITY INFORMATION**

<b>Quality Level A (QL-A) — Highest Quality</b>	
<b>A</b>	Positive identification of the attribute and location of a subsurface utility to an absolute spatial position in three dimensions. Achieved via potholing (Non-Destructive Digging). This is the highest quality level and the only method that provides confirmed depth, alignment, and service type.
<b>Quality Level B (QL-B) — Electronic Location</b>	
<b>B</b>	Relative subsurface feature location in three dimensions obtained via electromagnetic frequency (EMF) detection methods or Ground Penetrating Radar (GPR). Provides depth estimate and alignment but requires pothole verification before construction.
<b>Quality Level C (QL-C) — Surface Correlation</b>	
<b>C</b>	Approximate location and attributes of a subsurface utility asset derived from a combination of existing records and a site survey of visible surface evidence, such as alignment between valves, hydrants, pits, and marker posts.
<b>Quality Level D (QL-D) — Records Only</b>	
<b>D</b>	Lowest quality level. Attribute information compiled from any, or a combination of, existing records, site inspections, or anecdotal evidence — for example, alignment taken from BYDA plans or other service authority drawings. High risk of damage. Do not rely on this level for excavation.

**Service Colour Coding (AS 5488.1 / ASNZS 1319)**

Colour	Service Type
ORANGE	Electrical (HV & LV)
WHITE	Telecommunications / Communications
YELLOW	Gas
BLUE	Water (Potable)
PURPLE	Recycled Water
CREAM	Sewer / Rising Sewer Main
PINK	Unknown / Unidentified
GREEN	Stormwater

**■ IMPORTANT — UTILITY LOCATING PROCESS & DUTY OF CARE**

<b>1</b>	<b>Order Utility Plans</b>	Order FREE BYDA utility plans at <a href="http://www.byda.com.au">www.byda.com.au</a> before any works commence. Ensure all plans are present and in date.
<b>2</b>	<b>Engage Utility Locator</b>	A utility locator electronically locates services to provide depth & alignment and produces a detailed utility map for damage prevention.
<b>3</b>	<b>Pothole Utilities with NDD</b>	Non-Destructive Digging (Hydro Vacuum Excavation) positively identifies the absolute location of all buried utilities prior to construction.
<b>4</b>	<b>Proceed With Project</b>	With utility plans, maps & pothole reports on site, you are ready to proceed safely. Contact Provac Australia: 1300 734 772   <a href="http://www.provac.net.au">www.provac.net.au</a>